



### GREEN

visible surface - powder coating



### RED

no powder / only light spray mist



powder on the gearing not allowed

### ATTENTION:

Do not powder-coat, especially in the toothing area, as this may impair the clamping function.